


# MELTING TEMPERATURES

120  
130  
140  
150  
160  
170  
180  
190  
200  
210  
220  
230  
240  
250  
260  
270  
280



PLA      PS      PP      PE      ABS      PET

